

N & W Global Vending Ltd. PO Box 25 Dudley Street BILSTON West Midlands WV14 0LF

Tel: 01902 355000 Fax: 01902 402272

## PROCEDURE FOR STATISTICS PRINTING BRIO & BRIO 250

- 1. Connect printer to RS232 socket on control board.
- 2. Turn on machine.
- 3. Press program button on control board. (Machine displays 'Complete Selection')
- 4. **Press program button again.** (Machine displays 'Present Fault')
- 5. **Press button 7.** (Machine displays 'Confirm?')
- 6. Turn on printer.
- 7. **Press button 2.** (Printing will now commence)
- 8. When printing has finished turn off the machine and the printer.
- 9. Disconnect printer from control board.

## Layout of buttons





