# WITTENBORG

# **TECHNICAL INFORMATION**

TYPE NO		TYPE			T.INO.
FB 55			Freshbrewer		FB55 WA01/01
SERIAL NUMBERS AFFECTED	0401550099	995		ISSUED BY W	Documentation/ ittenborg Reinfeld
SUBJECT	VMC Boar	-d		ISSUED FOR	R (X):
	VIVIC DUAL	u		Information	X

### VMC BOARD

#### **COMPONENTS CONCERNED:**

• <u>Part no.</u> <u>Designation</u>

**OLD:** 47180502 VMC Board FB55

**NEW:** 47180503 VMC Board FB55

#### **MODIFICATION:**

- The VMC Board has been modified. It contains:
  - 1) an additional circuit board
  - 2) 2 additional lines on the back of the circuit board

# **REASON:**

- see also Technical Information FB55 08/00
  - ref. 1) It could happen that settings specific to the customer were automatically reset to default.
  - ref. 2) It was possible that the excess current cut-off device for the brewer would not function, as the error message (E5) would be deleted from the display and the brewer continues the dispensing process due to the reset.

# **CONTACT PERSON:**

 Technical queries: Christian Stahl Ordering of spare parts: Tanja Lange

ÄA 4852

Page 1/1

30.03.2001	C. REIMERS	30.03.2001	D. HANNAPPEL
DATE:	PRODUCED BY:	DATE:	CHECKED BY: