## **Technical Information**

**Control Board** 

Machine Type: Optima, Ventura, Riocca, Eclipse, Fusion, Calico, Profile,

Contour

and Vision (non bean to cup)

**Subject: Control Board** 

Issue No. SI0005

**Description:** EL04429012

Serial No. Prefix: 1252

As from the above serial number prefix an issue 12-control board has been introduced. The part number is EL04429012 and it can be used on all machines listed above and as with all previous boards is backwards compatible.

For your information two links have been added, LK4 and LK5 and are situated to the right of the thermister plug, P9. The links are for payment system communication and the jumpers should be configured as follows:

Bean to cup machines: LK4 jumper on pins 1 and 2 LK5 jumper on pins 1 and 2

Non-bean to cup machines: LK4 jumper on pins 2 and 3 LK5 jumper on pins 2 and 3

Please note: On new issue 12 boards purchased as a spares item the payment system will be configured for bean to cup machines as standard and will need to be re-configured if fitting to non bean to cup.

For further information pleased contact the technical helpdesk on 01249667323

Technical Information nformation Technical cal Information Information Technical ical Information Information Technical ical Information ial Information Technical cal Information ation Technical Information ial Information Technica<sup>l</sup> nation Technical Information

Date: 06/01/03 echnical Information

on Technical Information



Chippenham, Wiltshire, SN14 6NQ England Tel: +44 (0)1249 444807 Fax: +44 (0)1249 444819 Email: sales@cranems.co.uk

Web: www.cranems.co.uk







